

VCDS

Windows Based VAG/VAS Emulator Running on Windows 11 x64
VCDS Version: Release 23.3.1(x64) Data version: 20230421 DS346.2
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000 000000

Self-Diagnosis Log
Saturday, 10, February, 2024, 14:40:38:00009

VIN: WAUZZZ8K9DA153352 License Plate:
Mileage: 177250km-110138mi Repair Order:

Chassis Type: 8K-AU48 (8R0)
Scan: 01 02 03 05 08 09 0E 14 15 16 17 19 1B 22 42 44 46 52 53 56
5F 62 69 6D 72 A9

VIN: WAUZZZ8K9DA153352 Mileage: 177250km-110138miles

01-Engine -- Status: OK 0000
02-Auto Trans -- Status: OK 0000
03-ABS Brakes -- Status: Malfunction 0010
04-Steering Angle -- Status: OK 0000
05-Acc/Start Auth. -- Status: OK 0000
08-Auto HVAC -- Status: Malfunction 0010
09-Cent. Elect. -- Status: Malfunction 0010
0E-Media Player 1 -- Status: OK 0000
14-Susp. Elect. -- Status: OK 0000
15-Airbags -- Status: OK 0000
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: OK 0000
19-CAN Gateway -- Status: OK 0000
1B-Active Steering -- Status: OK 0000
22-AWD -- Status: Malfunction 0010
42-Door Elect, Driver -- Status: Malfunction 0010
44-Steering Assist -- Status: OK 0000
46-Central Conv. -- Status: Malfunction 0010
52-Door Elect, Pass. -- Status: OK 0000
53-Parking Brake -- Status: OK 0000
56-Radio -- Status: Malfunction 0010
5F-Information Electr. -- Status: OK 0000
62-Door, Rear Left -- Status: OK 0000
69-Trailer -- Status: OK 0000
6D-Trunk Elect. -- Status: OK 0000
72-Door, Rear Right -- Status: OK 0000
A9-Struct. Borne Sound -- Status: OK 0000

VCDS
Self-Diagnosis Log
Saturday, 10, February, 2024, 14:40:38:00009
Page 2

VIN: WAUZZZ8K9DA153352 License Plate:

Address 01: Engine (J623-CGWC) Labels: 06E-907-551-CGW.clb
Part No SW: 8K5 907 551 D HW: 4H0 907 551
Component: 3.0l V6 TFSIH07 0004
Revision: --H07--- CVN: B54A28A6
Coding: 12250034043601020000
Shop #: WSC 05323 002 104857
ASAM Dataset: EV_ECM30TFS0218K5907551D 001004
ROD: EV_ECM30TFS0218K5907551D.rod
VCID: 377D9EDB8E4D8D2B3A-8062
VINID: 9D196AAAA21B2544411430C5084087404B

No fault code found.
Readiness: 0010 0001

Address 02: Auto Trans (J217) Labels: 0B5-927-156.clb
Part No SW: 8K2 927 156 L HW: 0B5 927 156 J
Component: 0B5 30TFSIRdW H01 0005
Revision: --H01--- CVN: 0000FB1D
Coding: 000001
Shop #: WSC 06335 000 00000
ASAM Dataset: EV_TCMDL501021 001010
ROD: EV_TCMDL501021.rod
VCID: 3F8DF6FBA67DB56BF2-806A

No fault code found.

VCDS
Self-Diagnosis Log
Saturday, 10, February, 2024, 14:40:38:00009
Page 3

VIN: WAUZZZ8K9DA153352 License Plate:

Address 03: ABS Brakes (J104) Labels: 8K0-907-379-V1.clb
Part No SW: 8K0 907 379 CK HW: 8K0 907 379 CK
Component: ESP8 quattro H09 0100
Revision: ----- Serial number: -----
Coding: 29ED4E
Shop #: WSC 05323 002 1048576
VCID: 04073917871B16B3EF-8050

1 Fault Found:

01324 - Control Module for All Wheel Drive (J492)

013 - Check DTC Memory

Freeze Frame:

Fault Status: 01101101

Fault Priority: 4

Fault Frequency: 1

Reset counter: 205

Mileage: 177253 km

Time Indication: 0

Date: 2024.02.10

Time: 14:12:32

Freeze Frame:

Hex Value: 0x00C0

Hex Value: 0x0782

Hex Value: 0x000E

Hex Value: 0x5093

Hex Value: 0x0000

Address 05: Acc/Start Auth. (J393) Labels: 8K0-907-064-05.clb
Part No SW: 8K0 907 064 KG HW: 8K0 907 064 FG
Component: BCM2 2.0 H11 0711
Revision: 00002001
Coding: 01A24040000000000000
Shop #: WSC 18092 002 1048576
VCID: 7F0DB6FBEEFD756BB2-802A

Subsystem 1 - Part No SW: 8K0 959 754 BH HW: 8K0 959 754 BH

Component: FBSAUDIB8 IDG H71 0083

Serial number: 0812000163369008

No fault code found.

VCDS
Self-Diagnosis Log
Saturday, 10, February, 2024, 14:40:38:00009
Page 4

VIN: WAUZZZ8K9DA153352 License Plate:

Address 08: Auto HVAC (J255) Labels: 8Kx-820-043-3Z.clb
Part No SW: 8K1 820 043 T HW: 8K1 820 043 T
Component: KLIMA 3 ZONEN H04 0121
Revision: C1000000 Serial number: 01171020121559
Coding: 6620028080
Shop #: WSC 06335 000 00000
VCID: 397998E3B0599B5BCC-806C

1 Fault Found:

00457 - Central Electronics Control Module / BCM (J519)

013 - Check DTC Memory

Freeze Frame:

Fault Status: 01101101

Fault Priority: 6

Fault Frequency: 1

Reset counter: 205

Mileage: 177253 km

Time Indication: 0

Date: 2024.02.10

Time: 13:58:37

VCDS
Self-Diagnosis Log
Saturday,10,February,2024,14:40:38:00009
Page 5

VIN: WAUZZZ8K9DA153352 License Plate:

Address 09: Cent. Elect. (J519) Labels: 8K0-907-063.clb
Part No SW: 8K0 907 063 DJ HW: 8K0 907 063 DJ
Component: BCM1 1.0 H16 0103
Revision: 09016001 Serial number: 00000038779102
Coding: 260000108034AFF0398140C300001D0D0F9CE70826090201000008004401070200020024000000
Shop #: WSC 05323 002 1048576
VCID: 7AFB47EFF5DF504385-802E

Subsystem 1 - Part No SW: 8K1 955 119 A HW: 8T1 955 119 Labels: 1KX-955-119.CLB
Component: WWS 171012 H07 0080
Serial number: SWF12100176262
Coding: 00FD11

Subsystem 2 - Part No SW: 8U0 955 559 B HW: 8U0 955 559 B Labels: 8U0-955-559.CLB
Component: G397_RLFS H06 0002
Serial number: 20656994
Coding: 02005D

Subsystem 3 - Part No SW: 8K0 941 531 AS HW: 8K0 941 531 AS
Component: E1 - LDS H03 0031
Serial number: 00000000000810125075

Subsystem 4 - Part No SW: 8K5 941 329 HW: 8K5 941 329
H01 0031

Subsystem 5 - Part No SW: 8K5 941 329 HW: 8K5 941 329
H01 0031

Subsystem 6 - Part No SW: 4H0 907 658 HW: 4H0 907 658
Component: AQ_Hum_Sensor H03 0003
Serial number: 5F384456000000000001

1 Fault Found:

01229 - A/C Humidity Sensor (G260)

014 - Defective

Freeze Frame:

Fault Status: 01101110

Fault Priority: 3

Fault Frequency: 1

Reset counter: 205

Mileage: 177253 km

Time Indication: 0

Date: 2024.02.10

Time: 13:58:40

VCDS
Self-Diagnosis Log
Saturday, 10, February, 2024, 14:40:38:00009
Page 6

VIN: WAUZZZ8K9DA153352 License Plate:

Address 0E: Media Player 1 (R41) Labels: Redir Fail!
Part No SW: 8X0 035 110 C HW: 8X0 035 110
Component: CDC-MP3-Pana H41 0490
Revision: 00000008
VCID: 2D51BCB3741137FB50-8078

No fault code found.

Address 14: Susp. Elect. (J250) Labels: None
Part No SW: 8R0 907 364 C HW: 8K0 907 364
Component: DAEMPFUNGS-SG H09 0054
Revision: 00000000 Serial number: 05101207820002
Coding: 050181
Shop #: WSC 06335 000 00000
VCID: 3A7B87EFB55F9043C5-806E

No fault code found.

Address 15: Airbags (J234) Labels: 8K0-959-655.clb
Part No SW: 8K0 959 655 N HW: 8K0 959 655 N
Component: AirbagVW-AU10 H45 0610
Serial number: 003KFD966RT% Dataset Number: 8K0909602Q 0001
Coding: 305244353630303030554A304C384B3053
Shop #: WSC 04690 002 1048576
ASAM Dataset: EV_AirbaECUVWAUDI010 003010
ROD: EV_AirbaECUVWAUDI010_003_AU48.rod
VCID: 489FED27F3B3F2D343-801C

Crash sensor for side airbag: driver side:
Serial number: 6334MSME716520723

Front Passenger's Side Airbag Crash Sensor:
Serial number: 6344MSME716532558

Rear Side Airbag Crash Sensor (on driver's side):
Serial number: 6352QSME0324455CC

Passenger side rear thorax airbag crash sensor:
Serial number: 6362QSME6E213C66S

Crash sensor for front airbag: driver side:
Serial number: 63732SME6B23277C6

Crash sensor for front airbag: front passenger side:
Serial number: 63832SME6B231254Y

No fault code found.

VCDS
Self-Diagnosis Log
Saturday, 10, February, 2024, 14:40:38:00009
Page 7

VIN: WAUZZZ8K9DA153352 License Plate:

Address 16: Steering wheel (J527) Labels: 8K0-953-568.clb
Part No SW: 8R0 953 568 S HW: 8R0 953 568 S
Component: Lenks.Modul H07 0171
Revision: 00000000 Serial number: 20121019000724
Coding: 000037
Shop #: WSC 06335 123 12345
VCID: 51A9C04308E9331B14-8004

Component: E221 - MFL H03 0004

No fault code found.

Address 17: Instruments (J285) Labels: 8T0-920-xxx-17.clb
Part No SW: 8K0 920 931 K HW: 8K0 920 931 K
Component: KOMBIINSTR. H35 0553
Revision: 00000000 Serial number: RBL77FL9D
Coding: 13A71100BB010008000000
Shop #: WSC 06335 000 00000
VCID: 366393DF8147742321-8062

No fault code found.

Address 19: CAN Gateway (J533) Labels: 8T0-907-468.clb
Part No SW: 8R0 907 468 H HW: 8R0 907 468 C
Component: GW-BEM 4CAN-M H11 0051
Revision: 1Y050025 Serial number: 2541Y12A05012E
Coding: 80CF07FF00
Shop #: WSC 06335 000 00000
VCID: 4487F917C79BD6B3AF-8010

Subsystem 1 - Part No SW: 8T0 915 181 HW: 8T0 915 181
Component: J367-BDMHella H03 8041
Serial number: 2001828201

Subsystem 2 - Part No SW: 8K0 959 663 HW: 8K0 959 663
Component: J532_DCDCStab H17 0042
Serial number: 12279000409011200181

No fault code found.

VCDS
Self-Diagnosis Log
Saturday, 10, February, 2024, 14:40:38:00009
Page 8

VIN: WAUZZZ8K9DA153352 License Plate:

Address 1B: Active Steering (J792) Labels: None
Part No SW: 8K0 907 144 K HW: 8K0 907 144 K
Component: DYNAMIKLENK. H06 0710
Revision: 52001005 Serial number: -----
Coding: 040100
Shop #: WSC 06335 000 00000
VCID: 377D9EDB864D8D2B3A-8062

No fault code found.

Address 22: AWD (J492) Labels: 8K0-907-163.clb
Part No SW: 8K0 907 163 B HW: 8K0 907 163 A
Component: 4 Wheel Drive H13 0100
Serial number: 000310120001442 Dataset Number: 8K0909104D 0025
ASAM Dataset: EV_AllWheelDiffeQSPCAN 003019
ROD: EV_AllWheelDiffeQSPCAN.rod
VCID: 2F6DA6BB761D45EB62-807A

1 Fault Found:

0258 - No Basic Setting
B2010 00 [137] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

MIL ON - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 2

Fault Frequency: 1

Reset counter: 205

Mileage: 177257 km

Date: 2024.02.10

Time: 14:33:41

VCDS
Self-Diagnosis Log
Saturday, 10, February, 2024, 14:40:38:00009
Page 9

VIN: WAUZZZ8K9DA153352 License Plate:

Address 42: Door Elect, Driver (J386) Labels: 8K0-959-793.clb
Part No SW: 8K0 959 793 P HW: 8K0 959 793 P
Component: TSG FA H02 0506
Revision: Serial number: 0000042164068
Coding: 011C02205C00410001
Shop #: WSC 06342 000 00000
VCID: 4D91DC3314D117FB70-8018

1 Fault Found:

03297 - Switch in Lock Cylinder; Driver Side

008 - Implausible Signal

Freeze Frame:

Fault Status: 01101000

Fault Priority: 3

Fault Frequency: 1

Reset counter: 205

Mileage: 177253 km

Time Indication: 0

Date: 2024.02.10

Time: 13:58:36

Address 44: Steering Assist (J500) Labels: 8K0-909-144.clb
Part No SW: 8K0 909 144 F HW: 8K0 909 144 B
Component: RCEPS H37 0507
Revision: 00001000 Serial number: 0013878235 Dataset Number: 8K0909852H 0023
Coding: 010000010001
Shop #: WSC 06334 000 00000
ASAM Dataset: EV_RCEPSAU48X 008014
ROD: EV_RCEPSAU48X_008.rod
VCID: 3467A9D79F3B66331F-8060

No fault code found.

VCDS
Self-Diagnosis Log
Saturday,10,February,2024,14:40:38:00009
Page 10

VIN: WAUZZZ8K9DA153352 License Plate:

Address 46: Central Conv. (J393) Labels: 8K0-907-064-46.clb
Part No SW: 8K0 907 064 KG HW: 8K0 907 064 FG
Component: BCM2 2.0 H11 0711
Revision: 00002001 Serial number: 0185453468
Coding: 0102062020BA3080803002368000000F
Shop #: WSC 06335 000 00000
VCID: 7F0DB6FBEEFD756BB2-802A

1 Fault Found:

01134 - Alarm Horn (H12)

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 2

Fault Frequency: 1

Reset counter: 205

Mileage: 177253 km

Time Indication: 0

Date: 2024.02.10

Time: 13:58:40

Address 52: Door Elect, Pass. (J387) Labels: 8K0-959-792.clb
Part No SW: 8K0 959 792 P HW: 8K0 959 792 P
Component: TSG BF H02 0506
Revision: Serial number: 0000041988813
Coding: 011C02205E00410001
Shop #: WSC 06342 000 00000
VCID: 4C97D137EFCB1EF367-8018

No fault code found.

Address 53: Parking Brake (----) Labels: 8K0-907-801-V2.clb
Part No SW: 8K0 907 801 L HW: 8K0 907 801 J
Component: EPB-4 H01 0003
Revision: ----- Serial number: 00000001190976
ASAM Dataset: EV_ParkiBrake 001027
ROD: EV_ParkiBrake_AU48.rod
VCID: 387F9DE78353825333-806C

No fault code found.

VCDS
Self-Diagnosis Log
Saturday, 10, February, 2024, 14:40:38:00009
Page 11

VIN: WAUZZZ8K9DA153352 License Plate:

Address 56: Radio (R) Labels: 4F0-035-0xx-56.clb
Part No SW: 4G0 035 056 E HW: 4G0 035 056
Component: Radio U STD H60 0093
Revision: AB001007 Serial number: 230JT0C2633138
Coding: 010003020100000001
Shop #: WSC 06335 000 00000
VCID: 23455A8B22D5F18BF6-8076

1 Fault Found:

02983 - Connection between Impedance Converter 1 and Window Antenna

011 - Open Circuit

Freeze Frame:

Fault Status: 01101011

Fault Priority: 5

Fault Frequency: 1

Reset counter: 205

Mileage: 177253 km

Time Indication: 0

Date: 2024.02.10

Time: 13:58:46

Freeze Frame:

Voltage: 12.40 V

Address 5F: Information Electr. (J794) Labels: 4E0-035-6xx-5F.clb
Part No SW: 8R1 035 666 C HW: 8R1 035 666 C
Component: H-BN-EU H44 0524
Revision: ----- Serial number: 205JZ0C7550445
Coding: 110100010206A1ED0580AB5E00000403E40100020000000000
Shop #: WSC 05323 002 1048576
VCID: 387F9DE78B53825333-806C

Subsystem 1 - Part No: 8R0 060 884 AH

Component: EUR 2012 1308

Subsystem 2 - Part No SW: 8R0 919 604 HW: 8R0 919 604

Component: DU7 High H41 0104

Serial number: A130JS0C2563631

Subsystem 3 - Part No SW: 8T0 919 611 B HW: 8T0 919 611 B

Component: E0380 Bedient H02 0020

Serial number: 00000001299003

Subsystem 4 - Part No: 8R0 060 961 C

Component: CD-Database 3638

No fault code found.

VIN: WAUZZZ8K9DA153352 License Plate:

Address 62: Door, Rear Left (J388) Labels: 8K0-959-795.clb
Part No SW: 8K0 959 795 G HW: 8K0 959 795 D
Component: TSG HL H01 0506
Revision: Serial number: 0000041541131
Coding: 010C02204000210001
Shop #: WSC 06335 000 00000
VCID: 4683E31FF1A7E4A3B1-8012

No fault code found.

Address 69: Trailer (J345) Labels: 8K0-907-383.clb
Part No SW: 8K0 907 383 E HW: 8K0 907 383 E
Component: Anhaenger H12 0100
Revision: 1A001001 Serial number: 00000367152893
Coding: 0100000000000000
Shop #: WSC 00000 000 00000
VCID: 366393DF8147742321-8062

No fault code found.

Address 6D: Trunk Elect. (J605) Labels: 8K9-827-851.clb
Part No SW: 8K9 827 851 A HW: 8K9 827 851 A
Component: J605 Master H52 0330
Revision: ----- Serial number: 8K9827851A
VCID: 3C7781F7BF6BAE73D7-8068

Subsystem 1 - Part No SW: 8K9 827 852 A HW: 8K9 827 852 A
Component: J756 Slave H52 0330
Serial number: 8K9827852A

No fault code found.

Address 72: Door, Rear Right (J389) Labels: 8K0-959-795.clb
Part No SW: 8K0 959 795 G HW: 8K0 959 795 D
Component: TSG HR H01 0506
Revision: Serial number: 0000041541144
Coding: 010C02204000210001
Shop #: WSC 06335 000 00000
VCID: 4683E31FF1A7E4A3B1-8012

No fault code found.

VCDS
Self-Diagnosis Log
Saturday,10,February,2024,14:40:38:00009
Page 13

VIN: WAUZZZ8K9DA153352 License Plate:

Address A9: Struct. Borne Sound (J869) Labels: 4H0-907-159.clb
Part No SW: 8K0 907 159 HW: 4H0 907 159 A
Component: SAS-GEN 2 H06 0005
Serial number: 120824200526
ASAM Dataset: EV_SoundActuaGen2AU64X 002005
ROD: EV_SoundActuaGen2AU64X_002.rod
VCID: 72EB6FCFA5AF2803CD-8026

No fault code found.

End------(Elapsed Time: 04:17)-----